

Application recommendations





Milling cutters

Power consumption for face milling cutters

Guide values in order to determine the necessary power for Hollfelder-Gühring face milling cutters

 Steel, low-alloyed and tempereed
 $\varnothing D = 63$ $z = 8$ $v_C = 80$

 Steel, low-alloyed and tempereed
 $\varnothing D = 125$ $z = 15$ $v_C = 80$



General formula list

Formula and abbreviations	Calculation of:
$\varnothing D$ Milling cutter [mm]	Cutting speed $v_C = \frac{\varnothing D \cdot \pi \cdot n}{1000}$
a_p axial depth of cut [mm]	Number of revolutions $n = \frac{v_C \cdot 1000}{\varnothing D \cdot \pi}$
a_e Width of cut [mm]	Feed rate $v_f = f_z \cdot n \cdot z$
v_C Cutting speed [m/min]	Feed rate per tooth $f_z = \frac{v_f}{n \cdot z}$
n Numbers of revolutions - S [min ⁻¹]	Processing time $T_C = \frac{L_m}{v_f}$
z Number of teeth	Rate of metal removal $Q = \frac{a_p \cdot a_e \cdot v_f}{1000}$
f_z Feed rate per tooth [mm]	Required drive power $P = \frac{a_p \cdot a_e \cdot v_f \cdot k_c}{60 \cdot 10^6 \cdot \eta}$
v_f Feed rate [mm/min]	
L_m Machining length [mm]	
T_C Machining time [min]	
Q Rate of metal removal [cm ³ /min]	
k_c Specific cutting force [N/mm ²]	
P Necessary power [kW]	
η Efficiency factor	