

ISO taper	MAS/BT	CAT taper	Straight shank
<p>4619 HMC 3000, p. 19 4213 with increased clamping force, p. 20</p>	<p>4620 HMC 3000, p. 21 4221 with increased clamping force, p. 22</p>	<p>4216 with increased clamping force, p. 23</p>	
<p>4301, p. 67</p>	<p>4244 MAS/BT, p. 68</p>	<p>4243 p. 68</p>	
<p>4317 GÜHROJET Weldon, p. 112 4322 Whistle-Notch, p. 113</p>	<p>4234 GÜHROJET Weldon, p. 114 4233 Whistle-Notch, p. 115</p>	<p>4087 use with straight shank GÜHROSYNC p. 84</p>	
<p>4318, p. 122</p>	<p>4245, p. 122</p>		
<p>4576 GÜHROSYNC p. 81</p>	<p>4577 GÜHROSYNC p. 82</p>		<p>4525 GÜHROSYNC p. 83 4524 GÜHROSYNC MQL p. 90 4326 Synchro chuck, straight shank with IC, p. 99 4340 Quick-change tapping chuck w/o IC, p. 101 4342 Quick-change tapping chuck with IC, p. 101</p>
<p>4729 GÜHROJET with peripheral cooling, p. 42 4738 p. 40</p>	<p>4739 p. 43</p>	<p>4764 p. 45 4765 GÜHROJET p. 46</p>	<p>4719 p. 47</p>