

MF DIN 374 6HX Компас стр. 33







d1 X P	d2	SW	dk	l1	12	Код №
	mm		mm	mm	mm	
M12 X1,50 M14 X1,50 M16 X1,50 M18 X1,50 M20 X1,50	12,000 14,000	7,00 9,00 9,00 11,00 12,00	10,500 12,500 14,500 16,500 18,500	100,00 100,00 100,00 110,00 125,00	22,00 22,00 22,00 24,00 25,00	12,007 14,007 16,007 18,007 20,007











