

Application recommendations

Inserts for boring bars



Guide values for surface finish

In order to select the right feedrate per tooth (fz) please pay also attention to the table below „Guide values for surface finish“.

Guide values for surface finish relative to feedrate and corner radius

