

Spare parts

Disk springs for cartridges

Drawing nr.	Part nr.	Code
E2619-1	20064	3,500
E2619-2	20064	4,000
E2619-3	20064	6,000

Threaded pins

Drawing nr.	Part nr.	Code
E2608-1	20062	1,401
E2608-2	20062	1,402
E2608-3	20062	1,403
E2610-1	20062	2,001
E2610-2	20062	2,002
E2610-3	20062	2,003
E2610-4	20062	2,004
E2610-5	20062	2,005
E2610-6	20062	2,006
E2612-1	20062	2,501
E2612-2	20062	2,502
E2612-3	20062	2,503
E2612-4	20062	2,504
E2612-5	20062	2,505
E2614-1	20062	3,001
E2614-2	20062	3,002
E2614-3	20062	3,003
E2614-4	20062	3,004
E2614-5	20062	3,005
E2614-6	20062	3,006
E2614-7	20062	3,007

Torx wrenches

Drawing nr.	Part nr.	Code
Tx5	1612	5,001
Tx6	1612	6,001
Tx8	1612	8,001
Tx15	1612	15,001

Cranked Torx wrench

Drawing nr.	Part nr.	Code
Tx6	1612	6,002

Torque wrenches adjustable

Drawing nr.	Part nr.	Code
E5000	20063	1,200
E5001	20063	6,000
E6000	20063	0,810

Torque wrenches not adjustable

Drawing nr.	Part nr.	Code
E5400-5	20063	0,450
E5400-6	20063	0,700
E5400-8	20063	1,400
E5400-15	20063	3,450
E6001	20063	0,150
E6002	20063	0,800

Torx-bits

Drawing nr.	Part nr.	Code
Tx5-bit	4917	5,000
Tx6-bit	4917	6,000
Tx7-bit	4917	7,000
Tx8-bit	4917	8,000
Tx9-bit	4917	9,000
Tx10-bit	4917	10,000
Tx15-bit	4917	15,000

Allen wrenches

Drawing nr.	Part nr.	Code
SW0,7	4921	0,700
SW0,9	4921	0,900
SW1,3	4921	1,300
SW1,5	4921	1,500
SW2,0	4921	2,000

Ordering example: E2619-1 = Ordering number 20064 3,500 (part nr. + code)