

# Spare parts

## Allen wrenches

Drawing nr.	Part nr.	Code
SW2,5	4921	2,500
SW3,0	4921	3,000
SW4,0	4921	4,000
SW5,0	4921	5,000
SW6,0	4921	6,000

## Clamping sets for countersinking tools, cartridges and boring bars

Drawing nr.	Part nr.	Code
E1001	20065	5,000
E1010	20050	3,000
E1014	20050	2,501
E1030	20066	5,000
E1031	20050	2,002
E1040	20050	3,500
E1060	20050	2,500
E1085	20050	2,001
E1092	20050	2,502
E1100	20050	1,601
E1112	20050	2,000
E1120	20050	1,602
E3441	20050	1,600

## Clamping sets for milling cutters

Drawing nr.	Part nr.	Code
E4119	20051	2,500
E4265	20051	2,000
E 5032	20051	2,501
E 5482	20051	2,502

## Clamping sets for drill and chamfering tools

Drawing nr.	Part nr.	Code
E4890	20067	2,000
E4991	20067	2,500

Ordering example: SW 5,0 = Ordering number 4921 5,000 (part nr. + code)

## Eccentric pins

Drawing nr.	Part nr.	Code
E4120	20052	2,501
E4349	20052	2,001

## Assembly crease for eccentric pins

Drawing nr.	Part nr.	Code
E5162	20053	1,000

## Coolant screws for milling cutters

Drawing nr.	Part nr.	Code
E3805	20054	40,001
E3806	20054	50,001
E4079	20054	80,001
E4121	20054	80,000
E4154	20054	63,000
E4192	20054	40,000
E4193	20054	32,000
E4230	20054	50,000
E4247-1	20054	100,000
E4247-2	20054	100,001
E4275-2	20054	160,000
E4275-1	20054	160,001

## Adapter for milling cutters

Drawing nr.	Part nr.	Code
E5005	20055	1,800