



# Предельные отклонения отверстий в мкм

Номинальный размер в мм св. до		G		H								J		
		6	7	6	7	8	9	10	11	12		6	7	8
0	3	+8	+12	+6	+10	+14	+25	+40	+60	+100		+2	+4	+6
		+2	+2	0	0	0	0	0	0	0		-4	-6	-8
3	6	+12	+16	+8	+12	+18	+30	+48	+75	+120		+5	+6	+10
		+4	+4	0	0	0	0	0	0	0		-3	-6	-8
6	10	+14	+20	+9	+15	+22	+36	+58	+90	+150		+5	+8	+12
		+5	+5	0	0	0	0	0	0	0		-4	-7	-10
10	18	+17	+24	+11	+18	+27	+43	+70	+110	+180		+6	+10	+15
		+6	+6	0	0	0	0	0	0	0		-5	-8	-12
18	30	+20	+28	+13	+21	+33	+52	+84	+130	+210		+8	+12	+20
		+7	+7	0	0	0	0	0	0	0		-5	-9	-13
30	50	+25	+34	+16	+25	+39	+62	+100	+160	+250		+10	+14	+24
		+9	+9	0	0	0	0	0	0	0		-6	-11	-15
50	80	+29	+40	+19	+30	+46	+74	+120	+190	+300		+13	+18	+28
		+10	+10	0	0	0	0	0	0	0		-6	-12	-18
80	120	+34	+47	+22	+35	+54	+87	+140	+220	+350		+16	+22	+34
		+12	+12	0	0	0	0	0	0	0		-6	-13	-20
120	180		+54	+25	+40	+63	+100	+160	+250			+18	+26	+41
			+14	0	0	0	0	0	0			-7	-14	-22
180	250		+61	+29	+46	+72	+115	+185	+290			+22	+30	+47
			+15	0	0	0	0	0	0			-7	-16	-25

Номинальный размер в мм св. до		JS				K			M		
		6	7	8	9	6	7	8	6	7	8
0	3	+3	+5	+7	+12,5	0	0	0	-2	-2	-4
		-3	-5	-7	-12,5	-6	-10	-14	-8	-12	-18
3	6	+4	+6	+9	+15	+2	+3	+5	-1	0	+2
		-4	-6	-9	-15	-6	-9	-13	-9	-12	-16
6	10	+4,5	+7,5	+11	+18	+2	+5	+6	-3	0	+1
		-4,5	-7,5	-11	-18	-7	-10	-16	-12	-215	-21
10	18	+5,5	+9	+13,5	+21,5	+2	+6	+8	-4	0	+2
		-5,5	-9	-13,5	-21,5	-9	-12	-19	-15	-18	-25
18	30	+6,5	+10,5	+16,5	+26	+2	+6	+10	-4	0	+4
		-6,5	-10,5	-16,5	-26	-11	-15	-23	-17	-21	-29
30	50	+8	+12,5	+19,5	+31	+3	+7	+12	-4	0	+5
		-8	-12,5	-19,5	-31	-13	-18	-27	-20	-25	-34
50	80	+9,5	+15	+23	+37	+4	+9	+14	-5	0	+5
		-9,5	-15	-23	-37	-15	-21	-32	-24	-30	-41
80	120	+11	+17,5	+27	+43,5	+4	+10	+16	-6	0	+6
		-11	-17,5	-27	-43,5	-18	-25	-38	-28	-35	-48
120	180					+4	+12				
						-21	-28				
180	250					+5	+13				
						-24	-33				